


RFC	REV. LET.	DATE	REVISION	CHECKED BY	INSPECTED BY	APPROVED BY
	A	9-19-42	TRACED FOR NAVY	WATSON	YOUNG	CHAP
59721	B1	4-24-74	MAT'L WAS 1020 STEEL. - -	BY:		
	B1		WAS 16 GA. (0598)	FOR ENCL		
	B2		HEAT TREATMENT & NOTE ADDED.	AHS		



SAE 1045 HRSS			1	
MATERIAL	DRAWING NUMBER	ITEM	NAME OF PART	
ELECTRO-MOTIVE DIVISION CHRYSLER CREDIT CORPORATION 300 SOUTH BROADWAY NEW YORK, N.Y. 10038, U.S.A.				
PLATE DOWN-RETAINER PLATE				
PART USED ON:				
REMARKS:				

TOLERANCE ON FRACTIONAL DIMENSIONS
CASTINGS
MACHINING $\pm .005$