

A	男	40	2	4	
		30	2	3	
	女	10	1	1.5	
		3	0.5	1	
	男	3150	5	5	
		1600	4	7	
		800	3	4	
		400	2	4	
		200	1.5	2	
	女	100	1	1.5	
B					
TESTING (±)					
2M		0	14	24	
12M		7	12	21	
B	男	12M	6	18	19
		8M	5	8	14
	女	4M	4	6	11
		2M	3	4	8
	男	1N	2	3	6
		315	1	2	4
		120	2	3	3
		30	1	2	3
		10	0	1	2
	女	B			
TESTING (±)					
2M		1.5	6.0	8.0	
12M		4.0	7.7	10.0	
12N		4.0	6.0	8.0	
A	男	4N	0.8	2.0	4.0
		2M	2.5	1.2	3.0
	女	12M	3.0	2.2	2.0
		315	0.5	0.5	1.2
	男	120	15	0.3	0.2
		30	0.1	0.2	0.5
		3-6	0.95	0.1	0.2
		B			
		TESTING (±)			
	男	GENERAL TOLERANCE			
GENERAL TOLERANCE					

[illegible]

Xk13	2013.10.31	ADDED NO.122 & 123 AND CHANGED QUANTITY	RN01001-U233	K.B.YANG	H.U.LEE	K.S.RYU	Dx17	2012.12.03	CORRECTED BOLT TYPE & SEALANT. MODIFIED PART Q'TY.	RN01001-U168	K.B.YANG	H.U.LEE	H.G.RJU	APP CHK	2012.07.24	ASSY	세로 배열	ARRANGEMENT, LUGG EQUIPMENT,	
Hx22	2013.03.05	JUMPER BRACKET LOCATION CHANGE - CORRECTED BALLAST. ADDED 17-120	RN01001-U207	K.B.YANG	H.U.LEE	K.S.RYU	Cx16	2012.11.07	CORRECTED ITEM NO.	RN01001-U179	K.B.YANG	H.U.LEE	H.G.RJU	CHK	2012.07.24	중품용 G.W	TITLE	UPPER FLOOR	
Gx8	2013.01.03	ADDED HARDWARE, REPLACED HOSE, CHANGED SEALANT.	RN01001-U150	K.B.YANG	H.U.LEE	K.S.RYU	Ax4	2012.10.04	SEPARATE ITEM NO.95 TO ITEM NO.103&104.	RN01001-U114	K.B.YANG	H.U.LEE	H.G.RJU	설계 DGN	M.B. YANG 2012.07.24	도면 번호	RME20001CVO	Ver. 00	RN01001
Fx8	2012.12.24	ADDED BALLAST CHANGED BOLT & WASHER.	RN01001-U119	K.B.YANG	H.U.LEE	K.S.RYU	Bx9	2012.09.03	MODIFIED ITEM NO.72. CORRECTED FASTENER Q'TY.	RN01001-U098	K.B.YANG	H.U.LEE	H.G.RJU	설계 DRG		Rev. -J	SCALE 1/20	4 SHEET 4 of 4	RME-
기 종 MARK	날 짜 DATE	내 容 DETAIL OF REVISION(E.C.ZONE)	설 계 번호 E.C.NO.	설 계 DGN	검 査 CHK	승 인 APP	기 종 MARK	날 짜 DATE	내 容 DETAIL OF REVISION(E.C.ZONE)	설 계 번호 E.C.NO.	설 계 DGN	검 査 CHK	승 인 APP	표 지 REF. NO.			HYUNDAI Rotem	현대로템주식회사	필요번호